


Insta-TEST[®] 6 Plus

50 Pool & Spa Test Strips

- FREE CHLORINE
- BROMINE
- TOTAL CHLORINE
- ALKALINITY
- pH
- TOTAL HARDNESS
- CYANURIC ACID

LaMotte
Just DIP & READ!



Code 3028

Made in USA

Immerse strip for **2 SECONDS**. Remove with **pads face up**. **SHAKE ONCE TO REMOVE EXCESS WATER**. Read immediately: FCI>TCl>Alk>pH>TH>CyA

| | | | | | | |
|---|-----|-----|-----|-----|------|------|
| FCI Free Chlorine ppm (Br) Bromine ppm | 0 | 0.5 | 1 | 3 | 5 | 10 |
| | (0) | (1) | (2) | (6) | (10) | (20) |

| | | | | | | |
|----------------------------------|---|-----|---|---|---|----|
| TCl Total Chlorine ppm | 0 | 0.5 | 1 | 3 | 5 | 10 |
|----------------------------------|---|-----|---|---|---|----|

| | | | | | | |
|------------------------------|---|----|----|-----|-----|-----|
| Alk Alkalinity ppm | 0 | 40 | 80 | 120 | 180 | 240 |
|------------------------------|---|----|----|-----|-----|-----|

| | | | | | | |
|--|-----|-----|-----|-----|-----|-----|
| pH | 6.2 | 6.8 | 7.2 | 7.8 | 8.4 | 9.0 |
| Purple color indicates excessive sanitizer | | | | | | |

| | | | | | |
|---------------------------------|---|-----|-----|-----|------|
| TH Total Hardness ppm | 0 | 100 | 250 | 450 | 800+ |
|---------------------------------|---|-----|-----|-----|------|

| | | | | | |
|--|---|----|-----|-----|-----|
| CyA Cyanuric Acid ppm | 0 | 40 | 100 | 150 | 250 |
| For best results, pH must be between 7.0-8.4 | | | | | |

- Keep wet fingers out of the bottle.
- Close cap lightly after removing strip.
- In pools, immerse strip to a depth of 6".
- In spas, turn off jets and immerse strip to a depth of 6".
- For best results read in natural daylight.
- Store in a cool, dry place.



LaMotte Company, Chestertown, MD 21620 USA
www.lamotte.com/insta